

1-26-06

1-26-06

hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*Kathi Howard* 1-26-06

Kathi Howard Date

*C9C*

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Serial No.: 10/705,350  
 Filed: November 10, 2003  
 Patent No.: 6,866,153 *B2*  
 Issued: March 15, 2005  
 Applicant(s): Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P. Dugan  
 Title: DISPOSABLE NET ASSEMBLIES FOR APPARATUS FOR COLLECTING FLOATING DEBRIS

Commissioner for Patents  
 P.O. Box 1450  
 Alexandria, VA 22313-1450

**Certificate**  
**FEB 02 2006**

ATTN: DECISION AND CERTIFICATE OF CORRECTION  
 BRANCH OF THE PATENT ISSUE DIVISION

**of Correction**

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
FOR PTO MISTAKE (37 CFR §1.322 (a))**

Sir:

Attached in duplicate form, is Form PTO-1050, with at least one copy being suitable for printing. The errors which appear in the Form PTO-1050 were typographical errors which occurred through the fault of the U.S. Patent and Trademark Office ("PTO").

The exact column and line number where the errors are shown in the patent are as follows:

Column 2, line 13 reads "...maybe configured such that, upon filling of the first trap..." and should read - ...may be configured such that, upon filling of the first trap... - .

*FEB 03 2006*

Column 9, line 61 reads "...prises the two side members each having an upstream and..." and should read - ...prises the two side members, each having an upstream and... - .

Column 10, lines 1-2 read "12. The assembly of claim 11 wherein the at least two members having the two side members each has an upstream..." and should read - 12. The assembly of claim 11 wherein the two side members each has an upstream... - .

Column 10, lines 5-6 read "13. The assembly of claim 12 wherein the at least two members having the two side members each has an outside..." and should read - 13. The assembly of claim 12 wherein the two side members each has an outside... - .

Column 10, lines 9-10 read "14. The assembly of claim 13 wherein the at least two members having the two side members each has an inside..." and should read - 14. The assembly of claim 13 wherein the two side members each has an inside... - .

Column 10, lines 13-14 read "15. The assembly of claim 12 wherein the at least two members having the two side members each has an inside..." and should read - 15. The assembly of claim 12 wherein the two side members each has an inside... - .

Column 10, lines 17-18 read "16. The assembly of claim 11 wherein the at least two members having the two side members each has an inside..." and should read - 16. The assembly of claim 11 wherein the two side members each has an inside... - .

Column 10, lines 25-26 read "18. The assembly of claim 17 wherein the at least two members having the two side members each has an outside..." and should read - 18. The assembly of claim 17 wherein the two side members each has an outside... - .

Column 10, lines 29-30 read "19. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read - 19. The assembly of claim 18 wherein the two side members each has an upstream... - .

Column 10, lines 34-35 read "20. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read - 20. The assembly of claim 18 wherein the two side members each has an upstream... - .

Column 10, lines 36-37 read "21. The assembly of claim 17 wherein the at least two members having the two side members each has an upstream..." and should read - 21. The assembly of claim 17 wherein the two side members each has an upstream... - .

Column 10, lines 40-41 read "22. The assembly of claim 10 wherein the at least two members having the two side members each has an upstream..." and should read -

FEB 03 2006

22. The assembly of claim 10 wherein the two side members each has an upstream...

Column 10, lines 44-45 read "23. The assembly of claim 22 wherein the at least two members having the two side members each has an outside..." and should read – 23. The assembly of claim 22 wherein the two side members each has an outside... – .

Column 10, line 50 reads "...prises the two side members each having an outside thereof..." and should read – ... prises the two side members, each having an outside thereof... – .

Column 10, lines 53-54 read "25. The assembly of claim 24 wherein the at least two members having the two side members each has an upstream..." and should read – 25. The assembly of claim 24 wherein the two side members each has an upstream... – .

Column 10, lines 57-58 read "26. The assembly of claim 25 wherein the at least two members having the two side members each has an inside..." and should read – 26. The assembly of claim 25 wherein the two side members each has an inside... – .

Please send the certificate to:

Joseph R. Jordan, Esq.  
Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
Cincinnati, Ohio 45202

If there is any further charge or credit due, please use Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By:   
Joseph R. Jordan, Reg. No. 25,686

WOOD, HERRON & EVANS, L.L.P.  
2700 Carew Tower  
Cincinnati, Ohio 45202  
(513) 241-2324

FEB 03 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 *B2*

DATED : March 15, 2005

INVENTOR(S) : Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 13 reads "...maybe configured such that, upon filling of the first trap..." and should read - ...may be configured such that, upon filling of the first trap... - .

Column 9, line 61 reads "...prises the two side members each having an upstream and..." and should read - ...prises the two side members, each having an upstream and... - .

Column 10, lines 1-2 read "12. The assembly of claim 11 wherein the at least two members having the two side members each has an upstream..." and should read - 12. The assembly of claim 11 wherein the two side members each has an upstream... - .

Column 10, lines 5-6 read "13. The assembly of claim 12 wherein the at least two members having the two side members each has an outside..." and should read - 13. The assembly of claim 12 wherein the two side members each has an outside... - .

Column 10, lines 9-10 read "14. The assembly of claim 13 wherein the at least two members having the two side members each has an inside..." and should read - 14. The assembly of claim 13 wherein the two side members each has an inside... - .

Column 10, lines 13-14 read "15. The assembly of claim 12 wherein the at least two members having the two side members each has an inside..." and should read - 15. The assembly of claim 12 wherein the two side members each has an inside... - .

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. **6,866,153**

No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

Page 1 of 3

FEB 03 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 *B2*

DATED : March 15, 2005

INVENTOR(S) : Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,  
James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, lines 17-18 read "16. The assembly of claim 11 wherein the at least two members having the two side members each has an inside..." and should read – 16. The assembly of claim 11 wherein the two side members each has an inside... – .

Column 10, lines 25-26 read "18. The assembly of claim 17 wherein the at least two members having the two side members each has an outside..." and should read – 18. The assembly of claim 17 wherein the two side members each has an outside... – .

Column 10, lines 29-30 read "19. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 19. The assembly of claim 18 wherein the two side members each has an upstream... – .

Column 10, lines 34-35 read "20. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 20. The assembly of claim 18 wherein the two side members each has an upstream... – .

Column 10, lines 36-37 read "21. The assembly of claim 17 wherein the at least two members having the two side members each has an upstream..." and should read – 21. The assembly of claim 17 wherein the two side members each has an upstream... – .

Column 10, lines 40-41 read "22. The assembly of claim 10 wherein the at least two members having the two side members each has an upstream..." and should read – 22. The assembly of claim 10 wherein the two side members each has an upstream... – .

Column 10, lines 44-45 read "23. The assembly of claim 22 wherein the at least two members having the two side members each has an outside..." and should read – 23. The assembly of claim 22 wherein the two side members each has an outside... – .

-----  
MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,866,153

No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

Page 2 of 3

FEB 03 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 *B2*

DATED : March 15, 2005

INVENTOR(S) : Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,  
James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, line 50 reads "...prises the two side members each having an outside thereof..." and should read - ... prises the two side members, each having an outside thereof... - .

Column 10, lines 53-54 read "25. The assembly of claim 24 wherein the at least two members having the two side members each has an upstream..." and should read - 25. The assembly of claim 24 wherein the two side members each has an upstream... - .

Column 10, lines 57-58 read "26. The assembly of claim 25 wherein the at least two members having the two side members each has an inside..." and should read - 26. The assembly of claim 25 wherein the two side members each has an inside... - .

-----  
MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,866,153  
No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

Page 3 of 3

FEB 03 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 *B2*

DATED : March 15, 2005

INVENTOR(S) : Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran, James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 13 reads "...maybe configured such that, upon filling of the first trap..." and should read - ...may be configured such that, upon filling of the first trap... - .

Column 9, line 61 reads "...prises the two side members each having an upstream and..." and should read - ...prises the two side members, each having an upstream and... - .

Column 10, lines 1-2 read "12. The assembly of claim 11 wherein the at least two members having the two side members each has an upstream..." and should read - 12. The assembly of claim 11 wherein the two side members each has an upstream... - .

Column 10, lines 5-6 read "13. The assembly of claim 12 wherein the at least two members having the two side members each has an outside..." and should read - 13. The assembly of claim 12 wherein the two side members each has an outside... - .

Column 10, lines 9-10 read "14. The assembly of claim 13 wherein the at least two members having the two side members each has an inside..." and should read - 14. The assembly of claim 13 wherein the two side members each has an inside... - .

Column 10, lines 13-14 read "15. The assembly of claim 12 wherein the at least two members having the two side members each has an inside..." and should read - 15. The assembly of claim 12 wherein the two side members each has an inside... - .

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,866,153

No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

Page 1 of 3

FEB 08 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 *B2*

DATED : March 15, 2005

INVENTOR(S) : Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,  
James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, lines 17-18 read "16. The assembly of claim 11 wherein the at least two members having the two side members each has an inside..." and should read – 16. The assembly of claim 11 wherein the two side members each has an inside... – .

Column 10, lines 25-26 read "18. The assembly of claim 17 wherein the at least two members having the two side members each has an outside..." and should read – 18. The assembly of claim 17 wherein the two side members each has an outside... – .

Column 10, lines 29-30 read "19. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 19. The assembly of claim 18 wherein the two side members each has an upstream... – .

Column 10, lines 34-35 read "20. The assembly of claim 18 wherein the at least two members having the two side members each has an upstream..." and should read – 20. The assembly of claim 18 wherein the two side members each has an upstream... – .

Column 10, lines 36-37 read "21. The assembly of claim 17 wherein the at least two members having the two side members each has an upstream..." and should read – 21. The assembly of claim 17 wherein the two side members each has an upstream... – .

Column 10, lines 40-41 read "22. The assembly of claim 10 wherein the at least two members having the two side members each has an upstream..." and should read – 22. The assembly of claim 10 wherein the two side members each has an upstream... – .

Column 10, lines 44-45 read "23. The assembly of claim 22 wherein the at least two members having the two side members each has an outside..." and should read – 23. The assembly of claim 22 wherein the two side members each has an outside... – .

-----  
MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,866,153  
No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

Page 2 of 3

FEB 03 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,866,153 *B2*

DATED : March 15, 2005

INVENTOR(S) : Richard R. Turner, Jr., Robert Kircher, Dennis R. Moran,  
James P. Dugan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, line 50 reads "...prises the two side members each having an outside thereof..." and should read - ... prises the two side members, each having an outside thereof... - .

Column 10, lines 53-54 read "25. The assembly of claim 24 wherein the at least two members having the two side members each has an upstream..." and should read - 25. The assembly of claim 24 wherein the two side members each has an upstream... - .

Column 10, lines 57-58 read "26. The assembly of claim 25 wherein the at least two members having the two side members each has an inside..." and should read - 26. The assembly of claim 25 wherein the two side members each has an inside... - .

-----  
MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,866,153  
No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

Page 3 of 3

FEB 03 2006 FEB 03 2006